82 MAINF

SUGARLOAF RGNL (See CARRABASSETT on page 62)

SWANS FLD (See DIXFIELD on page 64)

```
SWANS ISLAND
```

BANKS (ME5) 5 N UTC-5(-4DT) N44°09.92′ W68°25.69′ HALIFAX

NOTAM FILE BGR 2.0% up W RWY 10-28: 1500X30 (GRVL)

RWY 10. Tree

RWY 28: Thid dsplcd 300'. Bldg. RUNWAY DECLARED DISTANCE INFORMATION

RWY 10: TORA-1500 TODA-1500 ASDA-1500 LDA-1500 RWY 28: TORA-1500 TODA-1500 ASDA-1500 LDA-1200

AIRPORT REMARKS: Unattended. Prior to using arpt call 207-460-1113. All ops rstd to dalgt VFR only. Wildlife on or invof arpt. Rwy 10-28 +6' rock ledge 50' from centerline south side of arpt. Rwy 10 has +15' trees 50' rgt of centerline 430' from thId. Rwy 10-28 sfc rough with large stones, steep gradients and no line of sight between ends. Rock drainage swale across 600' from Rwy 28, approximately 40' wide at centerline.

AIRPORT MANAGER: 207-596-7500 COMMUNICATIONS: CTAF 122.9 APP/DFP CON 133 6

CLEARANCE DELIVERY PHONE: For CD ctc Bangor Apch at 207-561-2521.

HELIPAD H1: H40X40 (CONC)

HELIPORT REMARKS: Helipad coords 44 09 54.80N 68 25 48.80W; helipad elev 86'. Ingress and egress to helipad between 130° and 320° mag.

TURNER

TWITCHELL (3B5) 4 S UTC-5(-4DT) N44°11.34′ W70°13.97′

NEW YORK

NOTAM FILE BGR RWY 11-29: 2151X100 (TURF)

RWY 11: Road.

RWY 29: Trees.

RWY 12-30: H2104X50 (ASPH) S-8.5 0.3% up W

RWY 12. Trees RWY 30: Trees.

SERVICE: S4 FUEL 100LL, MOGAS

AIRPORT REMARKS: Attended 1300-2200Z‡. For fuel, maintenance or seaplane information call 207-225-3490 or 207-312-4165 for FBO. Emerg phone 207-312-4165. Turkeys, geese on or invof arpt. Rwy 12, first 300 of rwy unmarked. Rwy 11, +38' P-line 140-180' from thld marked with balls across apch. Rwy 29, +20' pole 145' from end of rwy, 30' right of centerline; +25' bldg 145' from end of rwy, 90' right of centerline. Rwy 12-30 numbers and centerline NSTD length and width.

AIRPORT MANAGER: 207-225-3490 COMMUNICATIONS: CTAF/UNICOM 122.8

APP/DEP CON 125.5

CLEARANCE DELIVERY PHONE: For CD ctc Portland Apch at 207-874-7320, when Apch clsd ctc Boston ARTCC at 603-879-6859.

WATERWAY 04W-22W: 10000X1000 (WATER)

WATERWAY 15W-33W: 5000X1000 (WATER)

TWITCHELL (See TURNER on page 82)

VAN BUREN SPB (Ø5B) 0 N UTC-5(-4DT) N47°09.54' W67°55.92' HAI IFAX

440 LRA NOTAM FILE BGR WATERWAY NW-SE: 4000X200 (WATER)

WATERWAY SE: Bridge.

SEAPLANE REMARKS: Unattended. Clsd Oct 15-May 15 yearly. Access difficult due to construction of new border patrol facility. Dock located near base of bridge. Flight Notification Service (ADCUS) available. U.S. Customs avbl 24 hrs, 207-868-3391.

AIRPORT MANAGER: 207-868-2886 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.